





396x396





PK 01
PK 11



PK 01/446x396x



h	FCPK-1	FCPK-2
27	████████	████████
36	████████	████████
46	████████	████████



PK 11/446x396x



h	FCPK-1	FCPK-2
27	████████	████████
36	████████	████████
46	████████	████████

PK 02
PK 12



PK 02/396x446x



h	FCPK-1	FCPK-2
27	████████	████████
36	████████	████████
46	████████	████████



PK 12/396x446x



h	FCPK-1	FCPK-2
27	████████	████████
36	████████	████████
46	████████	████████

PK 21
PK 22



PK 21/396x396x


h	FCPK-1	FCPK-2
22	████████	████████
27	████████	████████
36	████████	████████



PK 22/396x396x


h	FCPK-1	FCPK-2
22	████████	████████
27	████████	████████
36	████████	████████

PK 03
PK 31




$h=22, t=22$
 $h=27, t=27$
 $h=36, t=36$
 $h \geq 46, t=30, t1=40$

PK 03/396x396x
PK 31/396x396x



h	FCPK-1	FCPK-2	FCPK-3	*	*
22	████████	████████	████████		
27	████████	████████	████████		
36	████████	████████	████████		
46	████████	████████	████████		
56	████████	████████	████████		
66	████████	████████	████████		
76	████████	████████	████████		
86	████████	████████	████████		
96	████████	████████	████████		
116	████████	████████	████████		

PK 04





*Inne gatunki materiałów - patrz str. I.3
*For other steel types - see page no I.3

PK 04/396x396x

h	FCPK-1	FCPK-2
36	████████	████████
46	████████	████████

PK 05



PK 05/62x396x

h	FCPK-1
56	████████
66	████████
76	████████
86	████████
96	████████
116	████████